



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/980,661	10/02/2003	Thomas W. Schrepfer	243334-001	8751
30623 7590 01/24/2008 MINTZ, LEVIN, COHN, FERRIS, GLOVSKY AND POPEO, P.C. ONE FINANCIAL CENTER BOSTON, MA 02111				
EXAMINER NASSER, ROBERT L				
ART UNIT		PAPER NUMBER		
3735				
MAIL DATE		DELIVERY MODE		
01/24/2008		PAPER		

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.



UNITED STATES DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office

Address : COMMISSIONER FOR PATENTS

P.O. Box 1450

Alexandria, Virginia 22313-1450

APPLICATION NO./ CONTROL NO.	FILING DATE	FIRST NAMED INVENTOR / PATENT IN REEXAMINATION	ATTORNEY DOCKET NO.
09980661	10/2/2003	SCHREPFER ET AL.	243334-001

MINTZ, LEVIN, COHN, FERRIS, GLOVSKY
AND POPEO, P.C.
ONE FINANCIAL CENTER
BOSTON, MA 02111

EXAMINER

ROBERT L. NASSER

ART UNIT	PAPER
----------	-------

3735

20080122

DATE MAILED:

Please find below and/or attached an Office communication concerning this application or proceeding.

Commissioner for Patents

see attached

/Robert L. Nasser Jr/
Primary Examiner
Art Unit: 3735

The reply filed on 10/30/2007 is not fully responsive to the prior Office Action because of the following omission(s) or matter(s): it appears that further explanation and/or discussion is required on the enablement issue. Specifically, applicant states that through conductor 24 does not contact electrode 22, but rather connects to a bond pad 25 on the inner side of the electrode, in a recess 26. However, it is unclear what the bond pad is and whether it is insulated from the electrode or whether it is conductive. Rather than waste an action on this issue, the examiner requests that applicant phone the examiner to discuss or explain the invention. See 37 CFR 1.111. Since the above-mentioned reply appears to be *bona fide*, applicant is given **ONE (1) MONTH or THIRTY (30) DAYS** from the mailing date of this notice, whichever is longer, within which to supply the omission or correction in order to avoid abandonment. EXTENSIONS OF THIS TIME PERIOD MAY BE GRANTED UNDER 37 CFR 1.136(a).

Any inquiry concerning this communication or earlier communications from the examiner should be directed to ROBERT L. NASSER whose telephone number is (571)272-4731. The examiner can normally be reached on m-f 9-5.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Charles Marmor II can be reached on 571 272-4730. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see <http://pair-direct.uspto.gov>. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Robert L. Nasser Jr/
Primary Examiner
Art Unit 3735

RLN
January 21, 2008